

CASTER - 4 BOLT STYLE

TOOLS REQUIRED FOR ASSEMBLY

Socket set, Open end wrench set, Cordless drill with 3/8" socket bit (Magnetic recommended).

BEFORE ASSEMBLING THE WORKBENCH

Assembly of this bench will require 2 people. Read through the assembly instructions to familiarize yourself with the order in which the parts are assembled. We suggest that you clear & vacuum the area where the bench is to be assembled. It is important that the bench is assembled in the same sequence as instructed.

HARDWARE

All assembly hardware is provided.

STEP 1 MOBILE CASTER KIT OPTION

Attach caster to the bottom leg insert plate using (4) 5/16-18 x 1" hex head bolts, (8) washers, and (4) nylock nuts.



5/16-18 x 1"
Hex Head Bolt



5/16" Washer



Nylock Nut

x2

