




MG - Casters

TOOLS REQUIRED FOR ASSEMBLY 1/2"Wrench and 1/2" Socket

BEFORE ASSEMBLING THE WORKBENCH Read through the assembly instructions to familiarize yourself with the order in which the parts are assembled.

HARDWARE All assembly hardware is provided.



Place (1) 5/16 X 1-3/4" Hex Bolt through (1) 5/16" Flatwasher and stick them through one of the holes in the caster.



Stick the bolt and washer through one of the holes through the bottom of the cabinet.

On the other end place (1) 5/16" Flatwasher onto the Hext Bolt. Screw (1) 5/16" Locknut onto the Hex Bolt tighting the caster to the cabinet bottom.

Repeat steps 1-2 for all four holes on the caster and then repeat again for each caster that is to be connected to the cabinet.

